



AHEAD OF WHAT'S POSSIBLE™

CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001147

DATE: 05-Aug-2026

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS28E38G+T	DS28E39Q+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	DS28E38G+U	DS28E39Q+U	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	DS28E38G-W51+1T	DS28E39Q+T	05-Aug-2026	05-Aug-2026	The part was not released
Discontinuance	DS28E38G-W51+1U	DS28E39Q+U	05-Aug-2026	05-Aug-2026	The part was not released
Discontinuance	DS28E83G+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	DS28E83G+U	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	DS89C430-ENG+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	DS89C430-ENL+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	DS89C430-MNL+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	DS89C430-QNL+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	DS89C450-ENG+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	DS89C450-ENL+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	DS89C450-MNL+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	DS89C450-QNG+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	DS89C450-QNL+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1426EAI+	AD9609BCPZ-20	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1426EAI+CA7	N/A	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1426EAI+T	AD9609BCPZRL7-20	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452AAE+	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452AAE+C8H	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452AAE+T	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452AAE+TC8H	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452ATG+	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452ATG+C8J	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452ATG+CPX	MAX40109IAWE+T	05-Aug-2026	05-Aug-2026	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 05-Sep-2026

Discontinuance	MAX1452ATG+T	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452ATG+TC8J	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452ATG+TCPX	MAX40109IAWE+T	05-Aug-2026	05-Aug-2026	The part was not released
Discontinuance	MAX1452C/D	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452CAE+	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452CAE+C8H	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452CAE+T	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452CAE+TC8H	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452EAE+	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452EAE+T	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1452EVSYS#	N/A	29-Jul-2027	29-Jan-2028	EVKIT is No Longer Supported
Discontinuance	MAX1453C/DW-C10318	MAX40109IAWE+T	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1464AAI+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1464AAI+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX1464C/D+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX14830EVKIT#	N/A	29-Jul-2027	29-Jan-2028	EVKIT is No Longer Supported
Discontinuance	MAX32625MBED#	N/A	29-Jul-2027	29-Jan-2028	EVKIT is No Longer Supported
Discontinuance	MAX4234ASD+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4234ASD+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4234AUD+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4234AUD+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4234AUD/V+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4234AUD/V+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4490AUK+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4490AUK+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4490AXK+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4490AXK+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4491AKA+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4491AKA+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4491AUA+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4491AUA+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4492ASD+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4492ASD+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4492AUD+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4492AUD+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4614CPD+	MAX4620EPD+	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 05-Sep-2026

Discontinuance	MAX4614CSD+	MAX4620ESD+	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4614CSD+T	MAX4620ESD+	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4614CUD+	MAX4747EUD+	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4614CUD+T	MAX4747EUD+	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4614EPD+	MAX4620EPD+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4614ESD+	MAX4620ESD+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4614ESD+T	MAX4620ESD+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4614EUD+	MAX4747EUD+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4614EUD+T	MAX4747EUD+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4614EUD/GG8	MAX4747EUD+	12-Aug-2027	29-Jan-2028	Part can no longer be manufactured
Discontinuance	MAX4615CUD+	MAX4752EUD+	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4615CUD+T	MAX4752EUD+	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4615EUD+	MAX4752EUD+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4615EUD+T	MAX4752EUD+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4616CPD+	ADG513BNZ	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4616CSD+	ADG713BRZ	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4616CSD+T	ADG713BRZ	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4616CUD+	MAX4749EUD+	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4616CUD+T	MAX4749EUD+	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4616ESD+	ADG713BRZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4616ESD+T	ADG713BRZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4616EUD+	MAX4749EUD+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4616EUD+T	MAX4749EUD+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4617CPE+	MAX4581CPE+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4617CSE+	MAX4581CSE+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4617CSE+T	MAX4581CSE+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4617CUE+	ADG658YRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4617CUE+T	ADG658YRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4617ESE+	ADG658YRQZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4617ESE+T	ADG658YRQZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4617EUE+	ADG658YRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4617EUE+T	ADG658YRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4618CPE+	MAX4582CPE+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4618CSE+	MAX4582CSE+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4618CSE+T	MAX4582CSE+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4618CUE+	ADG659YRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 05-Sep-2026

Discontinuance	MAX4618CUE+T	ADG659YRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4618ESE+	ADG659YRQZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4618ESE+T	ADG659YRQZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4618EUE+	ADG659YRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4618EUE+T	ADG659YRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4619CPE+	MAX4583CPE+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4619CSE+	MAX4583CSE+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4619CSE+T	MAX4583CSE+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4619CUE+	ADG733BRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4619CUE+T	ADG733BRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4619ESE+	MAX4583ESE+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4619ESE+T	MAX4583ESE+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4619EUE+	ADG733BRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4619EUE+T	ADG733BRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4624EUT+	MAX4544EUT+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4624EUT+T	MAX4544EUT+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4625EUT+	MAX4544EUT+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4625EUT+T	MAX4544EUT+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4626EUK+	MAX4514EUK+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4626EUK+T	MAX4514EUK+	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4627EUK+	ADG701LBRJZ-REEL7	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4627EUK+T	ADG701LBRJZ-REEL7	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4634ETB+	N/A	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4634ETB+T	N/A	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4634EUB+	ADG704BRMZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4634EUB+T	ADG704BRMZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4635ETB+	N/A	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4635ETB+T	N/A	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4635EUB+	ADG736LBRMZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4635EUB+T	ADG736LBRMZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4635EUB/GG8	ADG736LBRMZ	12-Aug-2027	29-Jan-2028	Part can no longer be manufactured
Discontinuance	MAX4636ETB+	N/A	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4636ETB+T	N/A	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4636EUB+	ADG736LBRMZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4636EUB+T	ADG736LBRMZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4638ESE+	ADG608BRZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 05-Sep-2026

[illegible]

Discontinuance	MAX4653EUE+T	ADG713BRUZ	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4688EWT+	N/A	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4688EWT+T	N/A	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4852ETE+	MAX14779ATP+	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4852ETE+T	MAX14779ATP+	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4854HETE+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4854HETE+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4855ETE+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX4855ETE+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5105EEP+	AD5307ARUZ	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5105EEP+T	AD5307ARUZ	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5105EWP+	AD5307ARUZ	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5105EWP+T	AD5307ARUZ	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5106EEE+	AD5307ARUZ	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5106EEE+T	AD5307ARUZ	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5180BEEI+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5180BEEI+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5181BEEG+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5181BEEG+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5182BEEI+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5183BEEI+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5183BEEI+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5184BEEG+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5184BEEG+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5184ETG+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5184ETG+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5186BEEI+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5186BEEI+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5187BEEG+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5187BEEG+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5189BEEI+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5189BEEI+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5190BEEG+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5190BEEG+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX5715BOB#	N/A	29-Jul-2027	29-Jan-2028	EVKIT is No Longer Supported
Discontinuance	MAX6651EEE+	N/A	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 05-Sep-2026

Discontinuance	MAX6651EEE+T	N/A	12-Aug-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX6950CEE+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX6950CEE+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX6950EEE+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX6950EEE+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX6951EVKIT	N/A	29-Jul-2027	29-Jan-2028	EVKIT is No Longer Supported
Discontinuance	MAX6952EAX+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX6952EAX+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX6952EPL+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX6954AAX+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX6954AAX+T	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX6954APL+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX6954ATL+	N/A	29-Jul-2027	29-Jan-2028	Discontinuation due to closure of TSMC Fab 2 and Fab 5
Discontinuance	MAX9259EVKIT+	N/A	29-Jul-2027	29-Jan-2028	EVKIT is No Longer Supported
Discontinuance	MAX9260EVKIT+	N/A	29-Jul-2027	29-Jan-2028	EVKIT is No Longer Supported