

1. Purpose

This document describes the discontinuation of RM series Rotary due to low and no demand with supplying chain issue.

2. Discontinuation details

2.1 Part Numbers affected

Item Number	Description
RM100002BCB	SWITCH RM100002BCB
RM100772BCB	SWITCH RM100772BCB
RM101002BCB	SWITCH RM101002BCB
RM101772BCB	SWITCH RM101772BCB
RM102002BCB	SWITCH RM102002BCB
RM102772BCB	SWITCH RM102772BCB
RM103002BCB	SWITCH RM103002BCB
RM103772BCB	SWITCH RM103772BCB
RM104002BCB	SWITCH RM104002BCB
RM104772BCB	SWITCH RM104772BCB
RM105002BCB	SWITCH RM105002BCB
RM105772BCB	SWITCH RM105772BCB
RM106002BCB	SWITCH RM106002BCB
RM106772BCB	SWITCH RM106772BCB
RM107002BCB	SWITCH RM107002BCB
RM107772BCB	SWITCH RM107772BCB

2.2 Possible replacement

No replacement.

2.3 Reason for discontinuation

RM sales is not meeting the level of sales necessary to maintain the production tooling and its support.