

1 Products affected

Product hierarchy no.				Part no.	SBU	Product Type	Customer part no.
SBU	PG	PUG	Type				
01	001	023	0000000358	See list below	Circuit Protection	UHP	n/a

List of part numbers affected for type UHP				
3-139-122	3-139-123	3-139-124	3-139-125	3-139-126
3-139-127	3-139-128	3-139-129	3-139-130	3-139-131
3-139-132	3-139-133			

2 Type of change

- Change of material

3 Detailed description of change

- Change of fuse filler from Ceramic to Sand

4 Reason of change

This change is part of the continuous improvement process.

5 Release date

The change takes effect in week 03/2025 (Date code 2503 or higher on label).

6 Impact of change and recommended action

☐ Form

☐ Fit

☒ Function

No action required, as the technical specification is not affected (e.g. pre-arcing time and time-current-curves)

☐ Manufacturing

☐ Label

☐ Packaging

7 Reference Documents

Kind of document	Document Title
Data sheet	UHP

Product Change Notification					PCN UHP Change of filler		
owner	creation date	release date	released by	change order	rev	page	D10-085-598
hotiar	09.09.2024	09.10.2024	schulejo		A	1 of 1	