



Product Change Notification

Current Date: 21-Jun-2026

TE Connectivity

Product Change Notification: PCN-26-282919

PCN Date: 19-JUN-26

Location: Maisach-gernlinden

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)

SR2M / V23047 Relays

General Description of Changes

>>> Temporary CCC Marking Interruption Manufacturing Location Transfer <<< Dear valued customer, as part of the previously communicated manufacturing location transfer (PCN-26-274543), the new production site is currently being added to the China Compulsory Certificate (CCC). Due to an update in the certification process, completion of this step is taking longer than originally planned. As a result, products shipped from the new location starting 29th of June will be temporarily delivered without the CCC mark. TE Connectivity is fully aligned on completing the certification update, and shipments with CCC marking are expected to resume by end of July. Customers who prefer not to receive shipments without CCC marking are requested to inform their TE representative in writing at the earliest. A further update will be provided once CCC marking is reinstated.

Reason for Changes:

Addition of the new production site is taking longer than originally planned.

PCN Attributes:

Product Category:	Kind of Change:
Relays, Contactors & Switches	Revision Adjustment / Part Clarification
Change Feature:	Potential Customer Impact:
Clarification/Correction	
Remarks:	
Relays produced on 29th of June (2026-06-29) and onwards will be affected. (datecode 2627 and up)	

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):
	29-JUN-2026
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393258-1	NO			V23047-A1021-A501, V23047A1021A501			
1-1393258-5	NO			V23047-A1024-A501, V23047A1024A501			
1-1393258-7	NO			V23047-A1024-A511,,F97243-000,AMPS-1-1393258-7, V23047A1024A511			
1393258-2	NO			V23047-A1005-A501, V23047A1005A501			
1393258-4	NO			V23047-A1012-A501, V23047A1012A501			
1393258-5	NO			V23047-A1012-A511, V23047A1012A511			
3-1415006-1	NO			V23047-A1048-A501, V23047A1048A501			
7-1415006-1	NO			V23047-A1005-A511, V23047A1005A511			



Product Change Notification

Current Date: 21-Jun-2026

TE Connectivity

Product Change Notification: PCN-26-282919

PCN Date: 19-JUN-26

Location: Maisach-gernlinden

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)

SR2M / V23047 Relays

General Description of Changes

>>> Temporary CCC Marking Interruption Manufacturing Location Transfer <<< Dear valued customer, as part of the previously communicated manufacturing location transfer (PCN-26-274543), the new production site is currently being added to the China Compulsory Certificate (CCC). Due to an update in the certification process, completion of this step is taking longer than originally planned. As a result, products shipped from the new location starting 29th of June will be temporarily delivered without the CCC mark. TE Connectivity is fully aligned on completing the certification update, and shipments with CCC marking are expected to resume by end of July. Customers who prefer not to receive shipments without CCC marking are requested to inform their TE representative in writing at the earliest. A further update will be provided once CCC marking is reinstated.

Reason for Changes:

Addition of the new production site is taking longer than originally planned.

PCN Attributes:

Product Category:	Kind of Change:
Relays, Contactors & Switches	Revision Adjustment / Part Clarification
Change Feature:	Potential Customer Impact:
Clarification/Correction	
Remarks:	
Relays produced on 29th of June (2026-06-29) and onwards will be affected. (datecode 2627 and up)	

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):
	29-JUN-2026
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393258-1	NO		TYC1-1393258-1	V23047-A1021-A501, V23047A1021A501			
1-1393258-5	NO		TYC1-1393258-5	V23047-A1024-A501, V23047A1024A501			
1-1393258-7	NO		TYC1-1393258-7	V23047-A1024-A511,,F97243-000,AMPS-1-1393258-7, V23047A1024A511			
1393258-4	NO		TYC1393258-4	V23047-A1012-A501, V23047A1012A501			
1393258-5	NO		TYC1393258-5	V23047-A1012-A511, V23047A1012A511			