

Information note

N° 054/23

Dear customer,

With this Infineon Technologies AG information note, we would like to inform you about the following

Amendment of Environmental Flag with Change of Ordering Code (OPN# and SP#)

Infineon Technologies AG

Postal address D-81726 München Internet www.infineon.com Headquarters Am Campeon 1-15, D-85579 Neubiberg Phone +49 (0)89 234-0

Chairman of the Supervisory Board Dr. Herbert Diess

Management Board Jochen Hanebeck (CEO), Constanze Hufenbecher, Dr. Sven Schneider, Andreas Urschitz, Dr. Rutger Wijburg

Registered office Neubiberg Commercial register Amtsgericht München HRB 126492

Information note

N° 054/23

► **Products affected**

Please refer to attached affected product list
 “INF_054-23_[customer-no].pdf”

► **Detailed change information**

Subject Amendment of Environmental Flag with/without Change of Ordering Code (OPN# and SP#)

Reason To Reflect the Correct Environmental Flags at Production Sites for Each Product

Description

SP# and OPN#

<u>Old</u>	<u>New</u>																												
<table border="1"> <thead> <tr> <th>SP#</th> <th>OPN#</th> </tr> </thead> <tbody> <tr> <td>SP001555780¹</td> <td>IRF8707TRPBF</td> </tr> <tr> <td>SP001570644¹</td> <td>IRF9393TRPBF</td> </tr> <tr> <td>SP001577608¹</td> <td>IRF9321TRPBF</td> </tr> <tr> <td>SP001574936²</td> <td>IRF7380TRPBF</td> </tr> <tr> <td>SP001555398²</td> <td>IRF7465TRPBF</td> </tr> <tr> <td>SP001570494²</td> <td>IRF7807ZTRPBF</td> </tr> </tbody> </table>	SP#	OPN#	SP001555780 ¹	IRF8707TRPBF	SP001570644 ¹	IRF9393TRPBF	SP001577608 ¹	IRF9321TRPBF	SP001574936 ²	IRF7380TRPBF	SP001555398 ²	IRF7465TRPBF	SP001570494 ²	IRF7807ZTRPBF	<table border="1"> <thead> <tr> <th>SP#</th> <th>OPN#</th> </tr> </thead> <tbody> <tr> <td>SP005857158</td> <td>IRF8707TRPBFXTMA1</td> </tr> <tr> <td>SP005959509</td> <td>IRF9393TRPBFXTMA1</td> </tr> <tr> <td>SP005959349</td> <td>IRF9321TRPBFXTMA1</td> </tr> <tr> <td>SP005876268</td> <td>IRF7380TRPBFXTMA1</td> </tr> <tr> <td>SP005876284</td> <td>IRF7465TRPBFXTMA1</td> </tr> <tr> <td>SP005876286</td> <td>IRF7807ZTRPBFXTMA1</td> </tr> </tbody> </table>	SP#	OPN#	SP005857158	IRF8707TRPBFXTMA1	SP005959509	IRF9393TRPBFXTMA1	SP005959349	IRF9321TRPBFXTMA1	SP005876268	IRF7380TRPBFXTMA1	SP005876284	IRF7465TRPBFXTMA1	SP005876286	IRF7807ZTRPBFXTMA1
SP#	OPN#																												
SP001555780 ¹	IRF8707TRPBF																												
SP001570644 ¹	IRF9393TRPBF																												
SP001577608 ¹	IRF9321TRPBF																												
SP001574936 ²	IRF7380TRPBF																												
SP001555398 ²	IRF7465TRPBF																												
SP001570494 ²	IRF7807ZTRPBF																												
SP#	OPN#																												
SP005857158	IRF8707TRPBFXTMA1																												
SP005959509	IRF9393TRPBFXTMA1																												
SP005959349	IRF9321TRPBFXTMA1																												
SP005876268	IRF7380TRPBFXTMA1																												
SP005876284	IRF7465TRPBFXTMA1																												
SP005876286	IRF7807ZTRPBFXTMA1																												
<p>Product Barcode Label</p> <p>¹ Without ‘Completely Pb Free’ Flag Logo, but with ‘Halogen Free’ Flag Logo</p> <p>² Without “Halogen Free” Flag Logo, but with “Completely Pb Free” Flag Logo</p>	<p>With both “Completely Pb Free” Flag Logo, and “Halogen Free” Flag Logo</p>																												

► **Product identification**

Products to be identified via OPN#, SP#, Product Barcode Label

► **Impact of change**

No Impact on Electrical Performance of the Products

► **Attachments**

INF_054-23_[customer-no].pdf affected product list

Information note

N° 054/23

► **Intended start of delivery**

Immediate

If you have any questions, please do not hesitate to contact your local sales office.