



Customer Information Notification

CN-202602019I

Issue date: 18 Feb 2026

Effective date: 18 Feb 2026

Here's your personalized quality information concerning products our customers and partners purchased from Nexperia.

For more details please contact your respective Nexperia CSR/AM.



Notification of Change Implementation on PCN CN-202601025F

Notification information

On 01/23/2026 (CN-202601025F), we notified you of the planned release of additional assembly site ATSN (Seremban, Malaysia), in order to ensure continuity of supply. We have not received a response from you. Please be informed that we will start supplying parts from ATSN for both existing and new orders.

Why do we issue this notification?

To inform that Nexperia will start supplying from ATSN for CN-202601025F parts for both existing and new orders with immediate effect.

Management summary

Notification of Change Implementation on PCN CN-202601025F

Identification of affected products

The assembly site can be identified on the packing labels (outer box as well as reel-label) and (where applicable) by the vendor code in the product marking.

Impact

No impact to the product's functionality anticipated

Data sheet revision

No impact to existing datasheet

Additional information

[View Change Notification Online](#)

Contact and support

For all Quality Notification content inquiries, please contact your local Nexperia Sales Support Team.

For specific questions on this notice or the products affected please contact our specialist directly:]

In case of distribution, please contact you distribution partner.

About Nexperia B.V.

We at Nexperia are the efficiency semiconductor company. We deliver over 90 billion products a year and as such service thousands of global customers, both directly and through our extensive network of channel partners. We are at the heart of billions of electronic devices in the Automotive, Mobile, Industrial, Consumer, Computing, and Communication Infrastructure segments.

You have received this email because you are a designated contact or subscribed to Nexperia Quality Notifications. Nexperia shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

If you would like to adjust your mailing preferences, please click [here](#).

| SalesItem_name | SalesItem_orderablePartNumber | SalesOrder_customerPartNumber | ProductType_name |
|----------------|-------------------------------|-------------------------------|------------------|
| 934060849215 | BAS101S,215 | BAS101S,215 | BAS101S |
| 934060849215 | BAS101S,215 | 934060849215 | BAS101S |
| 933589500215 | BC807,215 | 933589500215 | BC807 |
| 933589500215 | BC807,215 | BC807,215 | BC807 |
| 933589690215 | BC850B,215 | BC850B,215 | BC850B |
| 933589690215 | BC850B,215 | 933589690215 | BC850B |
| 933589690235 | BC850B,235 | | BC850B |
| 933589750215 | BC857A,215 | 933589750215 | BC857A |
| 933589750215 | BC857A,215 | BC857A,215 | BC857A |
| 933478930215 | BCX70H,215 | BCX70H,215 | BCX70H |
| 933478930215 | BCX70H,215 | 933478930215 | BCX70H |
| 933478930235 | BCX70H,235 | 933478930235 | BCX70H |
| 933478930235 | BCX70H,235 | BCX70H,235 | BCX70H |
| 934063346215 | BZB84-B16,215 | | BZB84-B16 |
| 934063346235 | BZB84-B16VL | | BZB84-B16 |
| 934061698215 | BZB84-C13,215 | | BZB84-C13 |
| 933770370215 | BZX84-B12,215 | BZX84-B12,215 | BZX84-B12 |
| 933770370215 | BZX84-B12,215 | 933770370215 | BZX84-B12 |
| 934664111215 | BZX84-B2V4-QR | BZX84-B2V4-QR | BZX84-B2V4-Q |
| 934664111215 | BZX84-B2V4-QR | 934664111215 | BZX84-B2V4-Q |
| 934664130215 | BZX84-B2V7-QR | BZX84-B2V7-QR | BZX84-B2V7-Q |
| 934664104215 | BZX84-B33-QR | | BZX84-B33-Q |
| 934664091215 | BZX84-B4V7-QR | 934664091215 | BZX84-B4V7-Q |
| 933564710215 | BZX84-B5V6,215 | BZX84-B5V6,215 | BZX84-B5V6 |
| 933564710215 | BZX84-B5V6,215 | 933564710215 | BZX84-B5V6 |
| 933564710235 | BZX84-B5V6,235 | | BZX84-B5V6 |
| 934664120215 | BZX84-B6V2-QR | 934664120215 | BZX84-B6V2-Q |
| 933671130215 | BZX84-B6V8,215 | 933671130215 | BZX84-B6V8 |
| 933671130215 | BZX84-B6V8,215 | BZX84-B6V8,215 | BZX84-B6V8 |
| 934664039215 | BZX84-B7V5-QR | | BZX84-B7V5-Q |

| | | | |
|--------------|-------------------|------------------|------------------|
| 934664039235 | BZX84-B7V5-QVL | | BZX84-B7V5-Q |
| 933137470215 | BZX84-C11,215 | 933137470215 | BZX84-C11 |
| 933137470215 | BZX84-C11,215 | BZX84-C11,215 | BZX84-C11 |
| 933137470235 | BZX84-C11,235 | | BZX84-C11 |
| 933388250215 | BZX84-C13,215 | BZX84-C13,215 | BZX84-C13 |
| 933388250215 | BZX84-C13,215 | 933388250215 | BZX84-C13 |
| 933388250235 | BZX84-C13,235 | BZX84-C13,235 | BZX84-C13 |
| 933388250235 | BZX84-C13,235 | 933388250235 | BZX84-C13 |
| 934663949215 | BZX84-C24-QR | | BZX84-C24-Q |
| 934663949235 | BZX84-C24-QVL | | BZX84-C24-Q |
| 933516970215 | BZX84-C3V9,215 | BZX84-C3V9,215 | BZX84-C3V9 |
| 933516970215 | BZX84-C3V9,215 | 933516970215 | BZX84-C3V9 |
| 933516970235 | BZX84-C3V9,235 | BZX84-C3V9,235 | BZX84-C3V9 |
| 933516970235 | BZX84-C3V9,235 | 933516970235 | BZX84-C3V9 |
| 933137420215 | BZX84-C6V8,215 | BZX84-C6V8,215 | BZX84-C6V8 |
| 933137420215 | BZX84-C6V8,215 | 933137420215 | BZX84-C6V8 |
| 933137420235 | BZX84-C6V8,235 | | BZX84-C6V8 |
| 933137430215 | BZX84-C7V5,215 | BZX84-C7V5,215 | BZX84-C7V5 |
| 933137430215 | BZX84-C7V5,215 | 933137430215 | BZX84-C7V5 |
| 933137430235 | BZX84-C7V5,235 | 933137430235 | BZX84-C7V5 |
| 933137450215 | BZX84-C9V1,215 | BZX84-C9V1,215 | BZX84-C9V1 |
| 933137450215 | BZX84-C9V1,215 | 933137450215 | BZX84-C9V1 |
| 933137450235 | BZX84-C9V1,235 | BZX84-C9V1,235 | BZX84-C9V1 |
| 933137450235 | BZX84-C9V1,235 | 933137450235 | BZX84-C9V1 |
| 934664225215 | MMBZ15VAL-QR | MMBZ15VAL-QR | MMBZ15VAL-Q |
| 934664225215 | MMBZ15VAL-QR | 934664225215 | MMBZ15VAL-Q |
| 934664225235 | MMBZ15VAL-QVL | | MMBZ15VAL-Q |
| 934057672215 | PBSS8110T,215 | PBSS8110T,215 | PBSS8110T |
| 934057672215 | PBSS8110T,215 | 934057672215 | PBSS8110T |
| 934057672235 | PBSS8110TVL | 934057672235 | PBSS8110T |
| 934055236215 | PDTA114YT,215 | PDTA114YT,215 | PDTA114YT |
| 934055236215 | PDTA114YT,215 | 934055236215 | PDTA114YT |
| 934031050215 | PDTA143ET,215 | 934031050215 | PDTA143ET |
| 934031050215 | PDTA143ET,215 | PDTA143ET,215 | PDTA143ET |
| 934031030215 | PDTC144ET,215 | 934031030215 | PDTC144ET |
| 934031030215 | PDTC144ET,215 | PDTA143ET,215 | PDTC144ET |
| 934031030235 | PDTC144ETVL | PDTC144ET,215 | PDTC144ET |
| 934663716115 | PDZ3.6B-QX | | PDZ3.6B-Q |
| 934070276115 | PESD1IVN27-UX | PESD1IVN27-UX | PESD1IVN27-U |
| 934661479215 | PESD2CANFD24L-TR | PESD2CANFD24L-TR | PESD2CANFD24L-T |
| 934661479215 | PESD2CANFD24L-TR | 934661479215 | PESD2CANFD24L-T |
| | | | PESD2CANFD24LT-Q |
| 934665383215 | PESD2CANFD24LT-QR | 934665383215 | Q |

| | | | |
|--------------|-------------------|-------------------|------------------|
| 934665383215 | PESD2CANFD24LT-QR | PESD2CANFD24LT-QR | PESD2CANFD24LT-Q |
| 934058196215 | PESD3V3S2UT,215 | PESD3V3S2UT,215 | PESD3V3S2UT |
| 934058196215 | PESD3V3S2UT,215 | 934058196215 | PESD3V3S2UT |
| 934059103215 | PESD5V0U1UT,215 | 934059103215 | PESD5V0U1UT |
| 934059103215 | PESD5V0U1UT,215 | PESD5V0U1UT,215 | PESD5V0U1UT |
| 934060856215 | PESD5V0U2BT,215 | 934060856215 | PESD5V0U2BT |
| 934060856215 | PESD5V0U2BT,215 | PESD5V0U2BT,215 | PESD5V0U2BT |
| 933859210215 | PMBD7000,215 | PMBD7000,215 | PMBD7000 |
| 933859210215 | PMBD7000,215 | 933859210215 | PMBD7000 |
| 933859210235 | PMBD7000,235 | PMBD7000,235 | PMBD7000 |
| 933859210235 | PMBD7000,235 | 933859210235 | PMBD7000 |
| 933816490215 | PMBTA56,215 | PMBTA56,215 | PMBTA56 |
| 933816490215 | PMBTA56,215 | 933816490215 | PMBTA56 |
| 933816490235 | PMBTA56,235 | PMBTA56,235 | PMBTA56 |
| 934068152115 | PMEG6020EPASX | 934068152115 | PMEG6020EPAS |
| 934068152115 | PMEG6020EPASX | PMEG6020EPASX | PMEG6020EPAS |