

## Product Change Notification (PCN)

**Issue Date:** 16.09.2024  
**Implementation of change:** 16.09.2024

**Products affected:** 44R022... / 44R023... / 44R024... / 44R025... / 44R026...  
**Description of part:** 2 - 6 device sockets

**Description of change:** modified mounting cut-out, connections: 3.0 or 4.8 mm  
**Reason for change:** revision of tooling

**Please note:** Our homepage is already up to date according to the new version.

## Product Change Notification (PCN)

**Issue Date:** 16.09.2024  
**Implementation of change:** 16.09.2024

Variant	old version	new version
44R02-2		<p>see yellow marked dimensions</p>
		<p>see yellow marked dimensions</p>
		<p>see yellow marked dimensions</p>

## Product Change Notification (PCN)

Issue Date: 16.09.2024

Implementation of change: 16.09.2024

Variant	old version	new version
44R02-3		<p>see yellow marked dimensions</p>
		<p>see yellow marked dimensions</p>
		<p>see yellow marked dimensions</p>

## Product Change Notification (PCN)

Issue Date: 16.09.2024

Implementation of change: 16.09.2024

Variant	old version	new version
44R02-4		<p>see yellow marked dimensions</p>
		<p>see yellow marked dimensions</p>
		<p>see yellow marked dimensions</p>

## Product Change Notification (PCN)

Issue Date: 16.09.2024

Implementation of change: 16.09.2024

Variant	old version	new version
44R02-5		<p>see yellow marked dimensions</p>
		<p>see yellow marked dimensions</p>
		<p>see yellow marked dimensions</p>

## Product Change Notification (PCN)

Issue Date: 16.09.2024

Implementation of change: 16.09.2024

Variant	old version	new version
44R02-6		<p>see yellow marked dimensions</p>
		<p>see yellow marked dimensions</p>
		<p>see yellow marked dimensions</p>