



Product Change Notification

Current Date: 09-Jan-2025

TE Connectivity

Product Change Notification: PCN-25-231642

Customer: TTI Inc (1305175)

Location: Maisach-gernlinden

PCN Date: 09-JAN-25

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)
PLUG, 3, 4, 6, 9, 12 CIRCUIT, UNIVERSAL MATE-N-LOK and CAP, 3, 4, 9, 6, 12, 15 CIRCUIT, UNIVERSAL MATE-N-LOK(TM)

General Description of Changes
The listed part number will not implement with additional markings as mentioned in the previous PCN numbers PCN-24-224772, PCN-24-224771, PCN-24-221848, PCN-24-216801, and PCN-24-216802.

Reason for Changes:
For internal business purposes.

PCN Attributes:	
Product Category:	Kind of Change:
Connector Housings	Sales Status Change
Change Feature:	Potential Customer Impact:
Label/Marking Change	No Customer Impact
Remarks:	

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):
	11-JAN-2025
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480700-0	NO		1-480700-0F, TYC1-480700-0, G371731-1	"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342", "9036100-0023", "MSE04810"			
1-480700-9	NO		TYC1-480700-9				
1-480701-0	NO		TYC1-480701-0				
1-480701-2	NO						
1-480701-9	NO		TYC1-480701-9				
1-480702-0	NO		1-480702-0F, TYC1-480702-0	"475838-000", "AMPS-1-0480702-0"			
1-480703-0	NO		1-480703-0F, TYC1-480703-0	"190442-000", "AMPS-1-0480703-0"			
1-480703-2	NO			"AMPS-1-0480703-2", "C40335-000"			
1-480704-0	NO		1-480704-0F, TYC1-480704-0	"011142-000", "AMPS-1-0480704-0", "1-0480704-0"			
1-480704-1	NO		TYC1-480704-1				
1-480705-0	NO		TYC1-480705-0, 1-480705-0F	"1-0480705-0"			
1-480706-0	NO		TYC1-480706-0	"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
1-480706-2	NO		TYC1-480706-2				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480707-0	NO		1-480707-0F, TYC1-480707-0	"239040-000", "AMPS-1-0480707-0"			
1-480708-0	NO		TYC1-480708-0	"CM3789-000", "SIML-1-0480708-0"			
1-480708-2	NO		TYC1-480708-2				
1-480708-9	NO						
1-480709-0	NO		TYC1-480709-0, 1-480709-0F				
1-480711-0	NO		TYC1-480711-0				

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Affected Revision
480700	1-480700-0	TYC1-480700-0, 1-480700-0F, G371731-1	AT
480701	1-480701-0	TYC1-480701-0	AP
480703	1-480703-2		AN
480704	1-480704-0	1-480704-0F, TYC1-480704-0	AS
480705	1-480705-0	1-480705-0F, TYC1-480705-0	AR
480706	1-480706-0	TYC1-480706-0	AN
480707	1-480707-0	TYC1-480707-0, 1-480707-0F	AM
480708	1-480708-0	TYC1-480708-0	AS



Product Change Notification

Current Date: 09-Jan-2025

TE Connectivity

Product Change Notification: PCN-25-231642

PCN Date: 09-JAN-25

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)

PLUG, 3, 4, 6, 9, 12 CIRCUIT, UNIVERSAL MATE-N-LOK and CAP, 3, 4, 9, 6, 12, 15 CIRCUIT, UNIVERSAL MATE-N-LOK(TM)

General Description of Changes

The listed part number will not implement with additional markings as mentioned in the previous PCN numbers PCN-24-224772, PCN-24-224771, PCN-24-221848, PCN-24-216801, and PCN-24-216802.

Reason for Changes:

For internal business purposes.

PCN Attributes:

Product Category:	Kind of Change:
Connector Housings	Sales Status Change
Change Feature:	Potential Customer Impact:
Label/Marking Change	No Customer Impact
Remarks:	

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):
	11-JAN-2025
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480700-0	NO		1-480700-0F, TYC1-480700-0, G371731-1	"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342", "9036100-0023", "MSE04810"			
1-480701-0	NO		TYC1-480701-0				
1-480701-2	NO						
1-480702-0	NO		1-480702-0F, TYC1-480702-0	"475838-000", "AMPS-1-0480702-0"			
1-480703-0	NO		1-480703-0F, TYC1-480703-0	"190442-000", "AMPS-1-0480703-0"			
1-480703-2	NO			"AMPS-1-0480703-2", "C40335-000"			
1-480704-0	NO		1-480704-0F, TYC1-480704-0	"011142-000", "AMPS-1-0480704-0", "1-0480704-0"			
1-480705-0	NO		TYC1-480705-0, 1-480705-0F	"1-0480705-0"			
1-480706-0	NO		TYC1-480706-0	"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
1-480707-0	NO		1-480707-0F, TYC1-480707-0	"239040-000", "AMPS-1-0480707-0"			
1-480708-0	NO		TYC1-480708-0	"CM3789-000", "SIML-1-0480708-0"			
1-480708-9	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480709-0	NO		TYC1-480709-0, 1-480709-0F				
1-480711-0	NO		TYC1-480711-0				