

# Information note

N° 072/25

Dear customer,

With this Infineon Technologies AG information note, we would like to inform you about the following

## Extension of total storage time of Finished Goods to 5 years for SMD and WLCSP packages

### Infineon Technologies AG

Postal address D-81726 München

Chairman of the Supervisory Board Dr. Herbert Diess

Management Board Jochen Hanebeck (CEO), Elke Reichart, Dr. Sven Schneider, Andreas Urschitz, Dr. Rutger Wijburg

Registered office Neubiberg Commercial register Amtsgericht München HRB 126492

Headquarters Am Campeon 1-15, D-85579 Neubiberg

# Information note

N° 072/25

| - <b>Products affected</b>           | Please refer to attached affected product list<br>INF_072_25_[customer-no].pdf |                                                                                                                                                             |            |            |                                   |                                   |
|--------------------------------------|--------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------------|-----------------------------------|-----------------------------------|
| - <b>Detailed change information</b> |                                                                                |                                                                                                                                                             |            |            |                                   |                                   |
|                                      | <b>Subject</b>                                                                 | Extension of total storage time of Finished Goods to 5 years for SMD (Surface Mount Devices) and WLCSP (Wafer Level Chip-Scale Package) packages            |            |            |                                   |                                   |
|                                      | <b>Reason</b>                                                                  | We are able to improve our Finished Goods storage from 2 years to 5 years without having any impact to quality and performance                              |            |            |                                   |                                   |
|                                      | <b>Description</b>                                                             | <table><tr><th><u>Old</u></th><th><u>New</u></th></tr><tr><td>- Maximum storage time is 2 years</td><td>- Maximum storage time is 5 years</td></tr></table> | <u>Old</u> | <u>New</u> | - Maximum storage time is 2 years | - Maximum storage time is 5 years |
| <u>Old</u>                           | <u>New</u>                                                                     |                                                                                                                                                             |            |            |                                   |                                   |
| - Maximum storage time is 2 years    | - Maximum storage time is 5 years                                              |                                                                                                                                                             |            |            |                                   |                                   |
| - <b>Product identification</b>      | Storage time can be calculated by the printed date code on the label           |                                                                                                                                                             |            |            |                                   |                                   |
| - <b>Impact of change</b>            | Technical risk assessment and solderability tests done<br>No impact seen.      |                                                                                                                                                             |            |            |                                   |                                   |
| - <b>Attachments</b>                 | INF_072_25_[customer-no].pdf                                                   | affected product list                                                                                                                                       |            |            |                                   |                                   |
| - <b>Intended start of delivery</b>  | 2025-09-30                                                                     |                                                                                                                                                             |            |            |                                   |                                   |

If you have any questions, please do not hesitate to contact your local sales office.

Extension of total storage time of Finished Goods to 5 years for SMD and WLCSP packages

| Sales name         | SP number   | OPN                | Package      | Customer part number |
|--------------------|-------------|--------------------|--------------|----------------------|
| CY7C53120E4-40AXI  | SP005652147 | CY7C53120E4-40AXI  | PG-TQFP-44   | CY7C53120E4-40AXI    |
| CY7C53150-20AXI    | SP005652153 | CY7C53150-20AXI    | PG-TQFP-64   | CY7C53150-20AXI      |
| CY7C53150-20AXIT   | SP005652155 | CY7C53150-20AXIT   | PG-TQFP-64   | CY7C53150-20AXIT     |
| CY7C65211-24LTXI   | SP005641945 | CY7C65211-24LTXI   | PG-VQFN-24   | CY7C65211-24LTXI     |
| CY7C65213-28PVXIT  | SP005641955 | CY7C65213-28PVXIT  | PG-SSOP-28   | CY7C65213-28PVXIT    |
| CY7C65213-32LTXI   | SP005641957 | CY7C65213-32LTXI   | PG-VQFN-32   | CY7C65213-32LTXI     |
| CY7C65215-32LTXI   | SP005642581 | CY7C65215-32LTXI   | PG-VQFN-32   | CY7C65215-32LTXI     |
| CY7C65215A-32LTXIT | SP005642587 | CY7C65215A-32LTXIT | PG-VQFN-32   | CY7C65215A-32LTXIT   |
| CY7C65620-56LTXIT  | SP005642627 | CY7C65620-56LTXIT  | PG-VQFN-56   | CY7C65620-56LTXIT    |
| CY7C65621-56LTXCT  | SP005642631 | CY7C65621-56LTXCT  | PG-VQFN-56   | CY7C65621-56LTXCT    |
| CY7C65630-56LTXC   | SP005642643 | CY7C65630-56LTXC   | PG-VQFN-56   | CY7C65630-56LTXC     |
| CY7C65630-56LTXI   | SP005642647 | CY7C65630-56LTXI   | PG-VQFN-56   | CY7C65630-56LTXI     |
| CY7C65631-56LTXC   | SP005642651 | CY7C65631-56LTXC   | PG-VQFN-56   | CY7C65631-56LTXC     |
| CY7C68013A-100AXC  | SP005642671 | CY7C68013A-100AXC  | PG-TQFP-100  | CY7C68013A-100AXC    |
| CY7C68013A-100AXI  | SP005642675 | CY7C68013A-100AXI  | PG-TQFP-100  | CY7C68013A-100AXI    |
| CY7C68013A-128AXC  | SP005642677 | CY7C68013A-128AXC  | PG-TQFP-128  | CY7C68013A-128AXC    |
| CY7C68013A-128AXI  | SP005642679 | CY7C68013A-128AXI  | PG-TQFP-128  | CY7C68013A-128AXI    |
| CY7C68013A-56BAXC  | SP005642681 | CY7C68013A-56BAXC  | PG-VFBGA-56  | CY7C68013A-56BAXC    |
| CY7C68013A-56BAXCT | SP005645171 | CY7C68013A-56BAXCT | PG-VFBGA-56  | CY7C68013A-56BAXCT   |
| CY7C68013A-56LTXC  | SP005645173 | CY7C68013A-56LTXC  | PG-VQFN-56   | CY7C68013A-56LTXC    |
| CY7C68013A-56LTXCT | SP005645175 | CY7C68013A-56LTXCT | PG-VQFN-56   | CY7C68013A-56LTXCT   |
| CY7C68013A-56LTXI  | SP005645177 | CY7C68013A-56LTXI  | PG-VQFN-56   | CY7C68013A-56LTXI    |
| CY7C68013A-56PVXCT | SP005645183 | CY7C68013A-56PVXCT | PG-SSOP-56   | CY7C68013A-56PVXCT   |
| CY7C68014A-100AXC  | SP005645187 | CY7C68014A-100AXC  | PG-TQFP-100  | CY7C68014A-100AXC    |
| CY7C68014A-128AXC  | SP005645189 | CY7C68014A-128AXC  | PG-TQFP-128  | CY7C68014A-128AXC    |
| CY7C68014A-56LTXC  | SP005645191 | CY7C68014A-56LTXC  | PG-VQFN-56   | CY7C68014A-56LTXC    |
| CY7C68015A-56LTXC  | SP005645195 | CY7C68015A-56LTXC  | PG-VQFN-56   | CY7C68015A-56LTXC    |
| CY7C68053-56BAXI   | SP005645209 | CY7C68053-56BAXI   | PG-VFBGA-56  | CY7C68053-56BAXI     |
| CY7C924ADX-AXC     | SP005645223 | CY7C924ADX-AXC     | PG-TQFP-100  | CY7C924ADX-AXC       |
| CY7C9689A-AXC      | SP005645225 | CY7C9689A-AXC      | PG-TQFP-100  | CY7C9689A-AXC        |
| CYP15G0101DXB-BBXC | SP005652833 | CYP15G0101DXB-BBXC | PG-LFBGA-100 | CYP15G0101DXB-BBXC   |
| CYP15G0101DXB-BBXI | SP005652835 | CYP15G0101DXB-BBXI | PG-LFBGA-100 | CYP15G0101DXB-BBXI   |
| CYP15G0201DXB-BBXC | SP005652837 | CYP15G0201DXB-BBXC | PG-LFBGA-196 | CYP15G0201DXB-BBXC   |
| CYPD3125-40LQXIT   | SP005655933 | CYPD3125-40LQXIT   | PG-VQFN-40   | CYPD3125-40LQXIT     |
| CYPD3175-24LQXQT   | SP005656615 | CYPD3175-24LQXQT   | PG-VQFN-24   | CYPD3175-24LQXQT     |

|                   |             |                         |              |                   |
|-------------------|-------------|-------------------------|--------------|-------------------|
| CYPD3176-24LQXQT  | SP005656623 | CYPD3176-24LQXQT        | PG-VQFN-24   | CYPD3176-24LQXQT  |
| CYPD3177-24LQXQ   | SP005656625 | CYPD3177-24LQXQ         | PG-VQFN-24   | CYPD3177-24LQXQ   |
| CYPD3177-24LQXQT  | SP005656631 | CYPD3177-24LQXQT        | PG-VQFN-24   | CYPD3177-24LQXQT  |
| CYPD3178-24LQXQT  | SP005656639 | CYPD3178-24LQXQT        | PG-VQFN-24   | CYPD3178-24LQXQT  |
| CYPD4226-40LQXI   | SP005659039 | CYPD4226-40LQXI         | PG-VQFN-40   | CYPD4226-40LQXI   |
| CYPM1322-97BZXI   | SP005674123 | CYPM1322-97BZXI         | PG-VFBGA-97  | CYPM1322-97BZXI   |
| CYUSB3013-BZXC    | SP005657037 | CYUSB3013-BZXC          | PG-TFBGA-121 | CYUSB3013-BZXC    |
| CYUSB3014-BZXC    | SP005657045 | CYUSB3014-BZXC          | PG-TFBGA-121 | CYUSB3014-BZXC    |
| CYUSB3014-BZXI    | SP005657049 | CYUSB3014-BZXI          | PG-TFBGA-121 | CYUSB3014-BZXI    |
| CYUSB3014-BZXIT   | SP005657053 | CYUSB3014-BZXIT         | PG-TFBGA-121 | CYUSB3014-BZXIT   |
| CYUSB3035-BZXI    | SP005657097 | CYUSB3035-BZXI          | PG-TFBGA-121 | CYUSB3035-BZXI    |
| CYUSB3065-BZXC    | SP005657103 | CYUSB3065-BZXC          | PG-LFBGA-121 | CYUSB3065-BZXC    |
| CYUSB3065-BZXI    | SP005657105 | CYUSB3065-BZXI          | PG-LFBGA-121 | CYUSB3065-BZXI    |
| CYUSB3302-68LTXI  | SP005657111 | CYUSB3302-68LTXI        | PG-VQFN-68   | CYUSB3302-68LTXI  |
| CYUSB3304-68LTXC  | SP005657123 | CYUSB3304-68LTXC        | PG-VQFN-68   | CYUSB3304-68LTXC  |
| CYUSB3304-68LTXI  | SP005657127 | CYUSB3304-68LTXI        | PG-VQFN-68   | CYUSB3304-68LTXI  |
| CYUSB3304-68LTXIT | SP005657129 | CYUSB3304-68LTXIT       | PG-VQFN-68   | CYUSB3304-68LTXIT |
| CYUSB3314-88LTXC  | SP005657153 | CYUSB3314-88LTXC        | PG-VQFN-88   | CYUSB3314-88LTXC  |
| CYUSB3314-88LTXI  | SP005657157 | CYUSB3314-88LTXI        | PG-VQFN-88   | CYUSB3314-88LTXI  |
| CYUSB3314-88LTXIT | SP005657159 | CYUSB3314-88LTXIT       | PG-VQFN-88   | CYUSB3314-88LTXIT |
| CYUSB3314-BVXI    | SP005657163 | CYUSB3314-BVXI          | PG-VFBGA-100 | CYUSB3314-BVXI    |
| CYUSB4024-FCAXI   | SP006125778 | CYUSB4024FCAXIXQ<br>MA1 | PG-TFBGA-169 | CYUSB4024-FCAXI   |
| CYUSB4347-BZXC    | SP005660177 | CYUSB4347-BZXC          | PG-LFBGA-192 | CYUSB4347-BZXC    |