

Product Discontinuance Notification

This is to inform you that the affected product(s) will be discontinued since there is supply constraint. This product discontinuance will take effect immediately from the date of this notification.

PDN No: PDN24006 rev0

Title: Product discontinuance of Trench Schottky parts

Issue Date: 2024/9/20

If you have any questions concerning this change, please contact:

PDN Coordinator

Name : Sunnie Lin

E-Mail : sunnie.lin@ts.com.tw

Phone : +886 2 8913-1588 Ext. 2205

PDN Originator

Name : Chris Lin

E-mail : chris.lin@ts.com.tw

Phone: +886 2 8913-1588 Ext. 2406

Effectivity:

Last order date: Not available (Immediately discontinuance)

Last shipment date: Not available (Immediately discontinuance)

Product Category (Description):

The product of Trench Schottky by Taiwan Semiconductor Co., Ltd

Reason of Discontinuance:

End of Life (EOL)

1. No shipment record in 3 years
2. Raw material supply constraint

Affected Product:

Package	TSC P/N	New TSC P/N
TO-220AB	TST10H100CW	TST10102C
ITO-220AB	TSF10H100C	TSF10102C
TO-220AB	TST20U100C	TST20102C
ITO-220AB	TSF20U100C	TSF20102C
ITO-220AB	TSF30U100C	TSF30102C
ITO-220AB	TSF40H100C	TSF40102C
TO-220AB	TST10H120CW	TST10122C
ITO-220AB	TSF10H120C	TSF10122C
TO-220AB	TST20H120CW	TST20122C
ITO-220AB	TSF20H120C	TSF20122C
TO-220AB	TST30H120CW	TST30122C
ITO-220AB	TSF30H120C	TSF30122C
TO-220AB	TST40L120CW	TST40122C
ITO-220AB	TSF40H120C	TSF40122C
SMPC4.0	TSPB15U45S	TSUP10M45SH
SMPC4.6	TSP10H60S	TSUP10M60SH
SMPC4.0	TSPB5H150S	None
SMPC4.6	TSP3H150S	None
SMPC4.6	TSP15H150S	None
SMPC4.6	TSP10H200S	None
SMPC4.6	TSP15H200S	None
SMPC4.0	TSPB15U50S	TSUP15M45SH
SMPC4.6	TSP10H45S	TSUP10M45SH
SMPC4.6	TSP10U60S	TSUP10M60SH
SMPC4.6	TSP15U50S	TSUP15M45SH