



Product Change Notification: CAAN-09WFXZ952

Date:

11-Feb-2026

Product Category:

32-Bit Microcontrollers, 8-Bit Microcontrollers

Notification Subject:

CCB 8041 Initial Notice: Qualification of CRM-1076WA as a new die attach material for selected AT58H01A, AT91R48, AT91SAM7S32C, AT91SAM7S65, AT91SAM7SE32, AT91SAM7SE32B, AT91SAM7Sxxx, ATSAM3Nxx, ATSAM3S2A, ATSAM3S4A, ATSAM3S4C, ATSAM3S8B, ATSAM3S8C, ATSAM3SD8B, ATSAM3SD8C, ATSAM3Sxx, ATSAM3U1C, ATSAM3U1E, ATSAM3U2E, ATSAM3U4E, ATSAM3X4C, ATSAM3X8C and ATSAM3X8E device families available in various packages assembled at ASSH site.

Affected CPNs:

[CAAN-09WFXZ952_Affected_CPN_02112026.pdf](#)

[CAAN-09WFXZ952_Affected_CPN_02112026.csv](#)

PCN Status: Initial Notification

PCN Type: Manufacturing Change

Microchip Parts Affected: Please open one of the files found in the Affected CPNs section.

Note: For your convenience Microchip includes identical files in two formats (.pdf and .xls)

Description of Change: Qualification of CRM-1076WA as a new die attach material for selected AT58H01A, AT91R48, AT91SAM7S32C, AT91SAM7S65, AT91SAM7SE32, AT91SAM7SE32B, AT91SAM7Sxxx, ATSAM3Nxx, ATSAM3S2A, ATSAM3S4A, ATSAM3S4C, ATSAM3S8B, ATSAM3S8C, ATSAM3SD8B, ATSAM3SD8C, ATSAM3Sxx, ATSAM3U1C, ATSAM3U1E, ATSAM3U2E, ATSAM3U4E, ATSAM3X4C, ATSAM3X8C and ATSAM3X8E device families available in various packages assembled at ASSH site.

Pre and Post Summary Changes:

	Pre Change	Post Change	Change (Yes/No)
--	------------	-------------	--------------------

Method to Identify Change: Traceability Code

Qualification Plan: Please open the attachments included with this PCN labeled as PCN_#_Qual_Plan.

Revision History: February 11, 2026: Issued initial notification.

Note: The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable product.

Attachments:

[PCN_CAAN-09WFXZ952_Qual Plan.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN):

AT58H01A-01
AT91R40008-66AU
AT91R40008-66AU-999
AT91SAM7S128D-AU-999
AT91SAM7S256D-AU-999
AT91SAM7S32C-AU
AT91SAM7S512B-AU
AT91SAM7S512B-AU-999
AT91SAM7S64C-AU
AT91SAM7S64C-AU-999
AT91SAM7SE32B-AU
AT91SAM7SE32B-AUR
ATSAM3N00AA-AU
ATSAM3N00AA-AUR
ATSAM3N00BA-AU
ATSAM3N00BA-AUR
ATSAM3N0AA-AU
ATSAM3N0AA-AUR
ATSAM3N0BA-AU
ATSAM3N0BA-AUR
ATSAM3N0CA-AU
ATSAM3N0CA-AUR
ATSAM3N1AB-AU
ATSAM3N1AB-AUR
ATSAM3N1BB-AU
ATSAM3N1BB-AUR
ATSAM3N1CB-AU
ATSAM3N1CB-AUR
ATSAM3S1AB-AU
ATSAM3S1AB-AUR
ATSAM3S1BB-AU
ATSAM3S1BB-AUR

CAAN-09WFXZ952 - CCB 8041 Initial Notice: Qualification of CRM-1076WA as a new die attach material for selected AT58H01A, AT91R48, AT91SAM7S32C, AT91SAM7S65, AT91SAM7SE32, AT91SAM7SE32B, AT91SAM7Sxxx, ATSAM3Nxx, ATSAM3S2A, ATSAM3S4A, ATSAM3S4C, ATSAM3S8B, ATSAM3S8C, ATSAM3SD8B, ATSAM3SD8C, ATSAM3Sxx, ATSAM3U1C, ATSAM3U1E, ATSAM3U2E, ATSAM3S1CB-AU

ATSAM3S1CB-AUR

ATSAM3S2AA-AU

ATSAM3S2AA-AUR

ATSAM3S2BA-AU

ATSAM3S2BA-AUR

ATSAM3S2CA-AU

ATSAM3S2CA-AUR

ATSAM3S4AA-AU

ATSAM3S4AA-AUR

ATSAM3S4BA-AU

ATSAM3S4BA-AUR

ATSAM3S4CA-AU

ATSAM3S4CA-AUR

ATSAM3S8BA-AU

ATSAM3S8BA-AUR

ATSAM3S8CA-AU

ATSAM3S8CA-AUR

ATSAM3SD8BA-AU

ATSAM3SD8BA-AUR

ATSAM3SD8CA-AU

ATSAM3SD8CA-AUR

ATSAM3U1CB-AU

ATSAM3U1EB-AU

ATSAM3U2EA-AU

ATSAM3U4EA-AU

ATSAM3X4CA-AU

ATSAM3X8CA-AU

ATSAM3X8EA-AU