



EVERLIGHT Electronics Co., Ltd.
Attn: No.6-8, Zhonghua Road, Shulin Dist., New
Taipei City,23860, Taiwan

- PRODUCT/PROCESS CHANGE NOTIFICATION
 PRODUCT TERMINATION NOTIFICATION

PCN tracking number: **PCN20250722-01 - CN25070002**

DATE: 22/07/2025

Contact: Ray Yang

Title: PM

E-mail:

Phone:

Fax: +

Product influenced: Major change Minor change

Product Identification: (e.g., affected supplier part number(s), affected product lines including specific package types, product family):

EL816 · EL817 series products.

Customer part number(s) (optional, if not required per agreed to customer criteria):

N/A

Method, if applicable, of identifying changed product:

High temperature reflow soldering performance is slightly different

Reason for change(s):

- Products Package Outline Dimension
 Electrical/Optical Specification
 Material: Raw Material
 Equipment
 Data Sheet
 Packing:
 Other:

Detailed description:

Improve the electroplating bonding of the lead frame
change the plating layer
Functional area: Cu-Ni-Ag Non-functional area: Cu-Ni-Sn
Reduce the risk of tin stripping caused by the electroplating
supplier's cleaning process

Anticipated (positive and negative) impact on form, fit, function, quality, or reliability:

Attached change report

Supplier Qualification plan schedule and/or results, where applicable:

N/A

**EVERLIGHT Electronics Co., Ltd.**

Attn: No.6-8, Zhonghua Road, Shulin Dist., New Taipei City, 23860, Taiwan

Forecasted key milestones	Date
Date, if required, when qualification samples are available	22.07.2025
Date, if required, when final qualification data are available	--
Proposed First Ship Date for change	--
Last buy date	--
Execution date	22.01.2026
Customer acknowledgement of receipt within 30 days of delivery of the PCN:	
Customer:	<input type="checkbox"/> Approval for shipments before effective date
Name/Date:	E-mail/Address:
Title:	Phone/Fax:
Customer Comments:	
EVERLIGHT acknowledgement of receipt:	
RECORD BY:	DATE:

The document of individual PCN information will be retained for a minimum of 5 years.