

Product Change Notice: JW, DJ, LD-P, HE, LQ, DW Relays/SF Relays Slim Type Safety Mark Change

PCN.PG06.04.15.2024

04.15.2024

About This Notice: We would like to inform there will be changes in the Chinese safety standards CQC for several part numbers.

Effective Date: April 1, 2024

Change Details: The inner and outer labels changed due to the CQC mark change.

■ Inner & outer labels changed due to CQC mark change

● (example) Packing style (made in Japan/DW)

- Inner label Each carton
- Inner carton
- Outer label 2 pcs./each carton
- Outer carton

● (example) Inner label (made in Japan/DW)


● (example) Outer label (made in Japan/DW)

(Mixed examples)

1. Mixture of old & new inner labels
2. Mixture of old & new outer labels
3. Both 1 & 2

Please see image below for changes in each series.

Category	Product	Inner	Outer
Power Relays	JW Relays		
	DJ Relays		
	LD-P Relays		
	HE Relays		
	LQ Relays		
	DW Relays (made in Japan)		
	DW Relays (made in Thailand)		
Safety Relays	SF Relays Slim type		



Affected Parts:	See attached part number list.
Datasheet(s):	See attached
Notes:	Part numbers, pricing, and specifications remain unchanged.

